1. Standards and Quality Assurance	2
1.1 SQA Process Overview	\$
1.2 The NYSERDA Portal	;
1.3 Responding to a Photo Inspection	
1.4 Responding to Could Not Verify (CNV) Measures	4
1.5 Post Inspection Report	5
1.6 Responding to Corrective Action Required Tasks (CARs) 1	6

Standards and Quality Assurance



Standards and Quality Assurance

This guide provides instruction for contractors and builders regarding the Standards and Quality Assurance inspection process. The guides can be accessed using the Table of Contents below. In addition to the user guides, the first link is a recorded training session conducted in July of 2020 that highlights the Standards and Quality Assurance inspection process. If you have additional questions after reviewing this material, please reach out to inspections @nyserda.ny.gov.

Table of Contents

SQA Inspection Process Training Video

SQA Process Overview

The NYSERDA Portal

Responding to a Photo Inspection

Responding to Could Not Verify (CNV) Measures

Post Inspection Report

Responding to Corrective Action Required Tasks (CARs)


SQA Process Overview

Introduction

The **Standards and Quality Assurance (SQA)** module allows NYSERDA and contracted Quality Service Providers (QSPs) to identify projects that are eligible for field or photo inspections. A random sampling of projects are selected for inspection to verify that program and technical requirements have been met. The SQA module allows inspectors to document evidence of any non-conformance through photos and written documentation. Information collected by the inspector is uploaded into the Salesforce QA checklist and an inspection report is generated. The SQA module allows the Contractor/Builder to submit corrective action documentation as needed and for the program implementer (either initiative staff or an external company providing support) to respond.

SQA Process Steps

The diagram below outlines the **SQA Process Steps** for the complete inspection process. The standard inspection process is outlined in the All Inspections row. Additional requirements for **Photo Inspection** are outlined in the **Photo Inspections Only** row. Lastly, if an inspection requires **C orrective Actions**, this process is included in the Correct Action Required Path. Generally speaking, Inspections without major or critical failures will typically end at the Approve Inspection step in the All Inspections row. If there are any CAR Tasks, the process will include the **Corrective Action Required Path**.



Inspections

NYSERDA conducts a minimum of three field inspections for each new participating Contractor/Builder. New Contractors/Builders who have not passed three inspections are listed as **Provisional**. When they are in good standing after these inspections, their status updates to **Full**. After a Contractor/Builder receives **Full** status, NYSERDA reviews a random sample of projects for review. Contractors/Builders with a **Probationary** or **S** uspended status may have 100% of their projects inspected.

In general, users can only schedule inspections for completed projects. However, Salesforce can allow inspections on in-progress projects if the program/initiative requires.

Email Communications

Contractors and builders will always receive email communication about SQA inspections. When NYSERDA schedules a project for SQA, we will send an email to the contractor with the inspection date, time, and address. NYSERDA automatically sends emails for cancelled and rescheduled inspections. The **QSP QA Manager** - the designated manager from the QSP QA agency - approves and distributes inspection reports to the project applicant. In rare instances a Contractor/Builder may not be notified of an upcoming inspection upon the customer's request.

Quality Scoring

The SQA Salesforce module assigns a Quality Score (on a scale of 1 to 5) based on the inspection results. This score will be provided in the Inspection report that is generated after the Inspector completes the inspection. NYSERDA provides Contractors/Builders a link to the inspection report through Salesforce.

SQA Quality Score	Description
1 or 2	Signifies a Failed Inspection with major and/or critical deficiencies. The Contractor/Builder must provide evidence to NYSERDA that these deficiencies outlined in the Inspection Report were resolved. Inspections in this score range may also contain minor or incidental deficiencies that will still need resolution, though the Contractor/Builder is not required to provide evidence for resolution of these issues. The inspection score may be updated if the Major and/or critical deficiencies are contested and NYSERDA approves.
3, 4 or 5	Signifies a Passed Inspection with only minor or incidental deficiencies. The Contractor/Builder must correct these issues but is not required to provide evidence to NYSERDA.

SQA Inspection Process Training Video

SQA Home

The NYSERDA Portal

The NYSERDA Portal

Introduction

The **Standards and Quality Assurance (SQA)** module is built within Salesforce (also known as the NYSERDA Portal). All activity related to scheduling, conducting, reviewing and approving inspections, and managing corrective action responses and resolutions, is documented and managed from within Salesforce.

Logging into Salesforce

1. Access the portal login page at https://portal.nyserda.ny.gov/login.

NEW YORK STATE OF OPPORTUNITY.	ERDA
Username	
Log In Forgot Your Password?	Sign Up

2. Enter your Username and Password.

NEW YORK STATE OF OPPORTUNITY.	DA
Username	
emailsample@gmail.com.nyserda	
Password	
Log In	
Forgot Your Password?	Sign Up

-	lser am :	Your username is the email address used when creating your NYSERA Portal (Salesforce) account with .nyserda added to the end as shown in the example screenshot above
	ass /ord:	You created this password when registering for the NYSERDA Portal (Salesforce) account. If you have forgotten the password, click the Forgot Your Password? Link and follow the prompts to reset your password.

3. Below is an example of the NYSERDA Portal (Salesforce) Home page after logging in. Many of the menu options along the top will be reviewed throughout this guide and provide navigation access to other parts of the Standards and Quality Assurance Salesforce build.

Home	Submit a New Application	Projects	Project Invoices	Manage Users	Relationship	Project Inspections	Dashboards		
result,	020 - Governor Cuomo's PAU NYSERDA is pausing all on-s ency-related. Further guidanc	site work co	nducted by contract	tors for all our cle	an energy progr	ams through May 15, u			
My T	äsks						(Overdue	~
			You hav	ve no open tasks sch	eduled for this per	iod.			


Dashboard

The **Dashboard** page provides an overview of your projects and to the available reports for Contractors /Builders.

1. After logging into Salesforce, click the **Dashboards** tab to access the Dashboard.

Home	Submit a New Application	Projects	Project Invoices	Manage Users	Relationship	Project Inspections	Dashboards	
								_
4/17/	2020 Coverner Cuemeie PAL		ive Order and subs	aquent Executive		priority on the cafety a	ind health of every New Yorker. As a	
							unless defined as either essential or	
emer	gency-related. Further guidance	ce is availat	ole at: <u>https://www.n</u>	yserda.ny.gov/ny/	COVID-19-Res	ponse		
								_
Mv	Tasks						Overdue v	
			You have	ve no open tasks sch	eduled for this per	riod.		

2. The Dashboard includes several visual charts to help you track your projects.




в Click Refresh to update the dashboards and display the most up-to-date information

- Hover your mouse over any data elements in any graph to reveal a tooltip with granular details С
- D Each chart in the Dashboard has an underlying report that can be accessed by clicking the chart

Reports

To access all of the reports a Contractor/Builder has access to, follow the instructions below.

- 1. After logging into Salesforce, access the Dashboards tab.
- 2. Then click the Go to Dashboard List link.



3. Select the Program folder to access the report list. Once clicked, the reports will show to the right.

Home	Submit a New Application	Projects	Project Invoices	Manage Users	Relationship	Project Inspections	Dashboards	
Repo	orts & Dashboard	ds						
olders		NY Sun	Res Contractor R	leports				
Q, Find a	folder	Q Find	reports and dashboards			All Items	▼ All	Types
All Folder	' s Sun Res Contractor Dashboards	Action	Name ↑			D I	Folder	Created By
	Sun Res Contractor Dashboards		2018 Inspectio	n Scores		1	NY Sun Res Contr	Mangione, Jason
		•	2019 Inspectio	n Scores		1	NY Sun Res Contr	Mangione, Jason
		•	Contractor Ins	pection Dashboard	1.0	1	NY Sun Res Contr	Mangione, Jason
		•	m Invoices by Pa	yment Status2		1	NY Sun Res Contr	Mangione, Jason
		•	Mumber of Pro	jects by Utility		t i i i i i i i i i i i i i i i i i i i	NY Sun Res Contr	Mangione, Jason
		•	MYSUNRes-Pr	ojectsWithInspectio	on	T I I I I I I I I I I I I I I I I I I I	NY Sun Res Contr	User, Integration
		•	Copen Projects	with Completion D	eadline	1	NY Sun Res Contr	Mangione, Jason
		•	Photo Inspect	ion Score		1	NY Sun Res Contr	Mangione, Jason
		-	Status and Sys	stem Size		1	NY Sun Res Contr	Mangione, Jason
			Waiting for Re	sponse		1	NY Sun Res Contr	Mangione, Jason

4. Below is a list of all reports available to Contractors/Builders.

Description
High-level overview of completed inspections.
Overview of all photo inspection score over a set period of time.
List of all projects from 2018.
List of all projects from 2019.
Groups projects by invoice status and displays invoice amount.
Groups projects by project status and system size.
Lists all projects that require input/response for process participants.
Groups projects by electric utility company.
Lists all approved projects at risk for termination.
Lists all approved/completed field or photo inspection projects.

* Includes links to **Project** records ** Includes links to **Project** and **Invoice** records *** Includes links to **Project** and **Inspection** records

5. After accessing a report, use the Filters at the top of the page to define how the information in the report should be displayed.

Report Options:			- Time Frame			
Summarize information by: Completed Date	Show All projects	T	Date Field Application Date	۲	Range Custom From	To
Run Report Hide Details Printable	View Export Details					

Run Report	Click to update the report information based on the filters set.
Hide Details	Hides the details of each heading in the report table. Click again to unhide these details.
Printable View	Click to open the report in a print friendly format.
Export Details	Exports the report into an excel format.

6. Click any Underlined Link in a report table to open the corresponding Project Record.

Project: Project Name	Α	pplication Number	Current Application Status Date	Invoice Approval Date
Completed Date: January (9 records)				
Project Number 1	0	0000XXXXX	1/11/2017	1/11/2017
Project Number 2	0	0000XXXXX	1/30/2018	1/30/2018
Project Number 3	0	0000XXXXX	1/31/2018	1/31/2018
Project Number 4	0	0000XXXXX	1/3/2019	1/3/2019

SQA Process Overview

SQA Home

Responding to a Photo Inspection

Responding to a Photo Inspection

Introduction


Some NYSERDA Programs stipulate in their respective Program Manuals that Photo inspections may be scheduled. If Contractors or Builders are performing an installation for a project under a NYSERDA program that conducts Photo Inspections, Contractors or Builders should be taking photos of their work at the time of installation or during project completion, regardless if any future scheduled inspection will be a Field or Photo Inspection. These photos will only need to be uploaded to the Inspection Checklist when a Photo Inspection has been scheduled.

Email Communications

When NYSERDA requests a photo inspection, Contractors or Builders will upload photos to Salesforce. NYSERDA will review all uploads, provide a QA score, and issue CAR reports if necessary.

Contractors/Builders have fifteen (15) days to upload installation/project photos after receiving an email notification requesting a Photo Inspection and will be reminded, via email, on the sixteenth (16) day if photos are not submitted.

Below is an example of the NYSERDA email communication that contractors or builders will receive when the QSP QA Scheduler schedules a Photo Inspection. The highlighted links open the Salesforce page where users can provide evidence/photos*.



If Contractors/Builders use the link in the email notification to access the Project Inspection Record, they will not need to log into Salesforce and navigate themselves as outlined in section 2.2 and section 2.5 of this guide.

SQA Inspection Statuses

The SQA Module uses the following Statuses for scheduling, conducting and reviewing inspections. Users can filter projects through these statuses.

Status	Description
Not Schedule	A project with no scheduled inspection.
Scheduling in Progress	An inspection where scheduling has begun, but the scheduling procedure is incomplete.

Customer Non-R espo nsive	An inspection where the customer is not responding to contact efforts. Please note that there are several instances where a Scheduler, Inspector, or Program Implementer can identify the customer as non-responsive.
Scheduled	A scheduled field inspection (the Inspector has not submitted the inspection record). Scheduling an inspection automatically updates the record to this status.
Photos Requested	The Contractor or Builder must submit photos for a photo inspection request.
Photos Submitted	The Contractor or Builder has submitted photos for a photo review request.
Inspection Complete	A completed inspection where the Inspector has submitted the inspection record.
QA Manager Approval Needed	An inspection ready for QA Manager approval.
Report Issued – No Corrective Action Needed	The QA Manager has approved and issued the inspection report and there are no CAR-eligible failures (incidental and /or minor failures may remain).
Report Issued – Corre ctive Action Needed	The QA Manager has approved and issued the inspection report and CAR-eligible failures (major and/or critical) remain unresolved.
Program Implementer Approval Needed	The Contractor/Builder has submitted their response to a CAR and it is ready for Program Implementer approval.
Contractor Non- Resp onsive	The Contractor or Builder has not responded to NYSERDA's request for corrective actions on a project or has not responded to a photo review request. The Program Implementer or QA Manager manually changes the status of the inspection to this status.
Contested – QA Mana ger Review Needed	The Contractor or Builder has contested the validity of a failure (CAR-eligible or not) identified during the inspection and the Program Implementer has confirmed.
Contested – NYSERDA QA Manager Review Needed	An inspection that requires NYSERDA QA Manager review. These occur when a Contractor or Builder has contested the validity of a failure (CAR-eligible or not) identified during the inspection, and both the Program Implementer and QA Manager have confirmed.
Completed	A completed inspection (inspection record complete, all failures resolved, etc.)
Cancelled	An inspection cancelled at the customer's request.

Uploading Photos

1. After accessing the correct **Project Inspection Record** either by logging into Salesforce or clicking the link in the email notification, click the **Inspection Checklist** button to open the checklist where photos can be uploaded.

Home	Submit a New Application	Projects	Project Invoices	Manage Users	Relationship	Project Inspections	Dashboards	
2	Project Inspection PI-003555							Printable View
« Back	to List: Project Inspections			Notes & Attachr	ments [0]			
Proj	ect Inspection Detail		Inspection Checkl	Review Failed Ta	asks			

2. The first page of the Inspection Checklist outlines the first series of Inspection Tasks. Each series of Inspection Tasks is associate to a specific **Measure**, and each **Measure** is associated to a specific **Category**. There may be multiple **Categories** (and therefore multiple **M** easures and **Tasks**) assigned to an inspection.

	ombiner	- Not Inspected, CNV	– Cou		Ground	-	✓ ure due to	CNV, or N/A – Not A	20	necklist Ver	sion
#¦¦↓	Task	Code Reference	Р	F	N/I	CNV	N/A	Defect Category	F-CNV	Fixed	Action
1	Grounding electrode conductor is sufficiently sized.	[NEC Articles 250.66, 250122, 250.166 and 690.47(C)]						Major			
2	AC Combiner is properly grounded.	[NEC Articles 250.4, 250.8, 250.12 and 690.43]						Major			
3	Grounded conductor(s) are insulated from metal enclosure surfaces and the ground terminal inside combiner box.	[NEC Article 250.24(A)(5)]						Major			

3. To upload photos, scroll to the bottom of the Inspection Checklist Measure and click Choose File. To locate and select the photo(s) from your computer.

☐ Mark all unrated tasks as CNV ⑦	\Box Mark entire measure as N/A $oldsymbol{\Im}$	
Inspector Notes	Contractor Notes	
h		
	EDIT	
Upload Photos: Choose Files No file chosen		
There is no photo available for the selected measure.		
BACK TO INSPECTION	SUBMIT	SAVE & NEXT

4. After a photo is successfully uploaded to the Measure you will see it as a list item underneath the Choose File button.

Uploaded By	Date Uploaded	Action
Frank McCleneghen	5/22/2020 11:51 AM	DELETE
	Frank	Frank 5/22/2020 11:51

5. To advance to the next Measure, click the Save & Next button.

BACK TO INSPECTION	SUBMIT		SAVE & NEXT
	· · · · · · · · · · · · · · · · · · ·	-	

6. Repeat steps 3-5 above until the Save & Next button is no longer visible. This means you have reached the last page of the Inspection and can click Submit .

A Multiple photos can be uploaded for each Measure at the same time by simply selecting multiple photo files during the upload process.

Making Measures as Photo Not Applicable

There may be cases when a Measure in the Inspection Checklist should be marked as **Photo Not Applicable**. If you need to mark a Measure this way, follow the steps in the **Uploading Photos** section on this page but replace step 3 with the below instructions.

Check the Mark entire measure as N/A box. This will systematically mark all Tasks in the viewable Measure as N/A.

Additionally, Contractors/Builders should also click **Edit** underneath the Contractor Notes window to activate the text box and document a note in the Contractor Notes section as to why the Measure was marked as N/A. Be sure to hit **Save** when done with the note.

☐ Mark all unrated tasks as CNV ⑦	□ Mark entire measure as N/A ⑦
Inspector Notes	Contractor Notes
	EDIT

The NYSERDA Portal

SQA Home

Responding to CNV Measures

Responding to Could Not Verify (CNV) Measures

Introduction

If a photo that has previously been uploaded by a Contractor/Builder does not adequately provide information for the Inspector to assess the associated **Measure** was installed properly, the Inspector will mark the **Measure** as **Could Not Verify**. Once the Inspector has completed the inspection process and submitted their findings, Contractors/Builders will receive an email communication notifying them that a photo(s) associated with a **Measure(s)** must be re-submitted to show evidence of proper installation.

Instructions

- 1. To re-submit a photo, access the Inspection Report (PDF Document) from the Project Inspection Record. This report will help you easily and quickly identify all Tasks that are marked as CNV.
- 2. Next, access the Inspection Checklist for the Project Inspection. This can be done either by:
 - Clicking the link in the email notification
 - Logging into Salesforce, Accessing the Project Inspection Record and clicking on the Inspection Checklist.
- 3. Once in the Inspection Checklist, use the Category and Measure drop down fields, in conjunction with the Inspection report, to navigate to the first Task marked as CNV.
 Follow the process in the Unloading Photos section of this guide to unload new photos for each Measure where a Task was marked as

Follow the process in the **Uploading Photos** section of this guide to upload new photos for each **Measure** where a **Task** was marked as **CNV**.

4. Continue until all tasks marked as CNV have a newly uploaded photo, then click Back to Inspection and log out.

```
Responding to a Photo Inspection
```

SQA Home

Post Inspection Report

Post Inspection Report

Introduction

Once an inspection has been completed and submitted by the Inspector, an Inspection Report is generated and appended to the Inspection Record. An email is systematically sent to the Contractor/Builder with a link to the Inspection Report.

Below are examples of the heading for an Inspection Report for both a passed and failed inspection. In an actual Inspection Report, below the Pass /Fail heading displays details on all aspects of the inspection results.

Air Source Heat Pump Program							
FIELD INSPECTION RE	NEW YORK STATE OF OFFORTUNITY. NYSERDA						
	PP-00002299						
Application No.	Grade	Score (Maximum of 5)					
0000118777	Pass	5					

Air Source Heat Pump Program						
FIELD INSPECTION REPO	NEW YORK STATE OF OPPORTUNITY.					
PP-00002299						
Application No.	Grade	Score (Maximum of 5)				
0000118777 Fail 1						
CORRECTIVE ACTION REQUIRED						

Responding to CNV Measures

SQA Home

Responding to CARs

Responding to Corrective Action Required Tasks (CARs)

Introduction

Corrective Action Required (CAR) tasks may be assigned to specific Measures or Tasks for an inspection. CARs, in general, highlight major or critical deficiencies of the installation or project.

Contractors/Builders who receive CAR tasks related to a prior inspection must resolve all Critical and Major failed tasks. This may require performing additional work on the build site to fix any documented issues. Once these issues have been resolved, Contractors/Builders should follow the following process to update the inspection record.

Resolving Correction Actions (CARs)

 Contractors and Builders respond to Corrective Action Required (CAR) tasks through the Review Failed Tasks page in Salesforce. Access to this page can be found in the email communication sent to Contractors and Builders when an inspection uncovers CARs.

Home	Submit a New Application	Projects	Project Invoices	Manage Users	Relationship	Project Inspections	Dashboards	
2	Project Inspection PI-003555							Printable View
« Back	to List: Project Inspections			Notes & Attachn	nents [0]			
Proj	ect Inspection Detail		Inspection Checkli	Review Failed Ta	isks			


2. On the **Review Failed Tasks** page, use the side navigation bar to locate all CAR eligible failed tasks. Failed tasks that require a response are denoted with a **Red X** to the right of the task. The first failed task will already be visible.

Home Submit a New Application Projects	Project Invoices Manage Users Relation	ship Project Inspections Dashboards	
AC Combiner Grounding Grounding electrode conductor is sufficiently sized.	Inspection #: PI-011264	Customer Name:	Customer Address:
PICN-1078235 PICN-1078235 grounded. PICN-1078236	Defect Category: Major Task:	Corrective Action Required: Yes Failure:	Fixed: No Attachments: View
Ground Mounted	Grounding electrode conductor is sufficiently sized. Failure Description: Grounding electrode conductor	PICN-1078235 Failure Due To CNV: No	Inspection Report: View Notes
grounding devices must be Installed correctly. L PICN-1078281	(GEC) is missing or undersized. # ⊟↓ Date User	Action* Notes*	Attachments Action
	1 5/22/2020	None 🗸	Insert
	Showing 1 to 1 of 1 entries		
	SUBMIT		

3. For each CAR eligible failed task, click the Action dropdown list and select **Mark as Resolved**, then add a note in the **Notes** section. Finally, click **Insert** to update the failed task and open the attachment window.

#¦¦↓	Date	User	Action*	Notes*	Attachments	Action
1	5/22/2020		None 🗸			Insert

(1)



4. In the Attachment column, click the Paperclip icon to open the CAR Failure Review Attachment window.

#¦¦↓	Date	User	Action*	Notes*	Attachments	Action
1	5/22/2020		Mark As Resolved	test	Ø	Edit I Delete

5. Click Choose Files in the new window to locate the files on your computer. Choose the appropriate file(s) for upload.

Car Fallure Review Attachments	×
Upload Photos: Choose Files No file chosen	
* 1	
CLOS	SE

A Multiple files or photos can be uploaded at the same time. Simply select multiple files or photos during Step three of this section.

- 6. After a file is uploaded, a thumbnail of the file will display in the Attachment window. Click the Close button when complete.
- 7. After successfully responding to all Failed tasks, click Submit at the bottom of the page to submit your CAR replies for review.
- After resolving the CAR tasks, the Program Implementer will review the submitted resolution. If the resolution is approved, no further
 actions are necessary for that specific CAR tasks. If the resolution is denied, the Program Implemented will reach out to request
 additional corrections.
- 9. Complete the above steps for all other CAR tasks.

Contesting Corrective Actions (CARs)

To contest a failed task, follow step 1 and step 2 from the Resolving Corrective Actions (CARs) section on this page, then:

- 1. To contest a failed task, select Contest Rating from the Action dropdown list.
- 2. Follow all additional steps from the Resolving Corrective Actions (CARs) section until all CARs have been resolved or contested.
- 3. Contested Failed Tasks are either Denied or Upheld by Program Implementers during the review process.
- Contractors are still required to resolve any failed tasks if the Program Manager denies the contest.
- If the Program Implementer marks a Contest Failed Task as upheld, it will be escalated to the NYSERDA QA Manager.

Contested Failed Tasks that are upheld by the Program Implemented are escalated to the NYSERDA QA Manager who will also perform a review and either deny or uphold the contested failed task.

Contractors are still required to resolve any failed tasks if the NYSERDA QA Manager denies the contest.

- Contractors will receive a follow-up notification email regarding the CAR tasks and must respond by the Respond By date in the notification.
 Failed tasks can only be contested twice.

Post Inspection Report

SQA Home